ANALOG Product/Process Change Notice - PCN 18_0022 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Appendix A) that you may have purchased in the last 2 years. Any inquiries or requests with this PCN (additional data or samples) must be sent to ADI within 30 days of publication date. ADI contact information is listed below.

| PCN Title: | ADIS16495BMLZ / ADIS16497BMLZ Timing Spec Updates | | |
|-------------------|---|--|--|
| Publication Date: | 26-Jan-2018 | | |
| Effectivity Date: | 26-Jan-2018 | (the earliest date that a customer could expect to receive changed material) | |

Revision Description:

Initial Release

Description Of Change

Datasheet timing specifications change. See Supporting Document. Changes will be made in Rev B datasheet of ADIS16495 and ADIS16497

Reason For Change

Update timing specifications to account for timing changes across temperature. Currently timing specifications only listed for Tc = 25C. Now takes into account 85C (worst Case) as well.

Impact of the change (positive or negative) on fit, form, function & reliability

Start up, Data Ready Latency, Flash Updates and other timing specs slower than Released Rev A datasheet typical specifications.

Product Identification (this section will describe how to identify the changed material)

DateCodes 1731 or later

Summary of Supporting Information

Test correlation and validation will be performed per ADI's standard product site to site and/or platform change correlation procedure. See attached Qualification Plan.

Supporting Documents

Attachment 1: Type: Datasheet Specification Comparison

ADI_PCN_18_0022_Rev_-_Timing Spec Change.docx

| For questions on this PCN, please send an email to the regional contacts below or contact your local ADI sales representatives. | | | | | |
|---|-------------------------|---------|-----------------------|-------------------------|--|
| Americas: | PCN_Americas@analog.com | Europe: | PCN_Europe@analog.com | Japan: Rest of Asia: | PCN_Japan@analog.com PCN_ROA@analog.com |

| Appendix A - Affected ADI Models | | | | | |
|--|-----------------------------|-----------------------------|-----------------------------|-----------------------------|--|
| Added Parts On This Revision - Product Family / Model Number (7) | | | | | |
| ADIS16495 / ADIS16495-1BMLZ | ADIS16495 / ADIS16495-2BMLZ | ADIS16495/ADIS16495-2WBMLZX | ADIS16495 / ADIS16495-3BMLZ | ADIS16497 / ADIS16497-1BMLZ | |
| ADIS16497 / ADIS16497-2BMLZ | ADIS16497 / ADIS16497-3BMLZ | | | | |

| Appendix B - Revision History | | | | |
|-------------------------------|--------------|------------------|-----------------|--|
| Rev | Publish Date | Effectivity Date | Rev Description | |
| Rev | 26-Jan-2018 | 26-Jan-2018 | Initial Release | |
| | | | | |

Analog Devices, Inc.

Docld:4352 Parent Docld:None Layout Rev:7