



DS5002FPM Secure Microprocessor Chip

www.maxim-ic.com

REVISION C6 ERRATA

The errata listed below describe situations where DS5002FPM revision C6 components perform differently than expected or differently than described in the data sheet. Dallas Semiconductor intends to fix these errata in subsequent die revisions.

This errata sheet only applies to DS5002FPM revision C6 components. Revision C6 components are branded on the topside of the package with a six-digit code of the form yywwC6, where yy and ww are two-digit numbers representing the year and work-week of manufacture, respectively. To obtain an errata sheet on another DS5002FPM die revision, visit website at www.maxim-ic.com.

The M character at the terminus of the part number indicates that the device is a special version of the DS5002FP manufactured with a special top coating to discourage microprobing.

There are no errata on this device.